
From: Way, Steven
Sent: Monday, January 26, 2015 6:06 AM
To: Ostrander, David
Subject: FW: 1-25 photos from BTBS
Attachments: IMG1103.JPG; IMG1104.JPG; IMG1113.JPG; IMG1117.JPG

FYI

Steven Way
Federal On-Scene Coordinator
Emergency Response Unit
US EPA - Region 8
1595 Wynkoop Street
Denver, CO 80202

Office: 303-312-6723

Attached are four pictures from today.

IMG1103: Santec digging test pits.

IMG1104: Test pit #1 (closest to the creek) with oil seeping from groundwater.

IMG1113: Ineffective containment boom bellying at Black Tail Creek main channel.

IMG1117: Oil sheen in Black Tail Creek near US-85.

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.